



Defining the future of Mobile Healthcare.™

Customer Quote

Order No: Q686-00001

Quote Date: 1/12/2018

Expiration Date: 2/15/2018

Salesperson: Kasey Gillum

kgillum@frazerbilt.com

Invoice To:

Mesquite Fire Department
1101 E. Main St.
Mesquite TX 75149
US

Attention:

Captain
Brian Staples
bstaples@mesquitefire.org

Order Instructions:

Includes customer loyalty discount.

No.	Item	Quantity	U/M		Unit Price		Net Amount
1	MODULE Type I 12' Remount E-1733/X-742 Painting of the remount includes all new doors, latches and hinges.	1.000	EA	\$	85,450.00	\$	85,450.00
2	CHASSIS 2018 Ford F-350 Diesel	1.000	EA	\$	43,750.00	\$	43,750.00
3	DELIVERY Customer Pick Up - FOB Frazer	0.000	M	\$	2.75	\$	0.00
4	HGAC-RMT HGAC Fee for a Remounted Unit	1.000	EA	\$	600.00	\$	600.00



Defining the future of Mobile Healthcare.™

Customer Quote

Order No: Q686-00001

Quote Date: 1/12/2018

Expiration Date: 2/15/2018

Remit To:

Per TMVCC, we are quoting this through our
licensed franchise dealer, Sterling McCall Ford.

Sterling McCall Ford
6445 Southwest Freeway
Houston TX 77074

Sale Amount:	129,800.00
Order Disc(4.4684%):	-5,800.00
Sales Tax:	0.00
Total Amount:	124,000.00

Payment Terms: Net 30 Days

Special Instructions:

Email this quote along with your PO to sales@frazerbilt.com.
Graphics pricing includes two hours' design time in the base price.
More extensive graphics or multiple changes will be billed at \$100/hr.



Defining the future of Mobile Healthcare.™

For your convenience, all module pricing has been itemized below per quote Q686-00001 for Mesquite Fire Department :

Base Module	\$	18,000.00
Chassis Exterior	\$	15,200.00
Module Exterior	\$	28,350.00
Chassis Interior	\$	4,700.00
Module Interior	\$	19,200.00
Module Total	\$	85,450.00

Items included in above totals:

1. Type I 12' Module	\$	incl
----------------------	----	------

Chassis Exterior:

2. Heat Shielding for Diesel Chassis	\$	1,500.00
3. Chassis : 2018 Ford F-350 , Diesel , 4x2 , Regular Cab , 84" Cab to Axle , Ford White (FA90:YO)	\$	incl
4. Suspension: LiquidSpring	\$	10,500.00
5. Wheel type: Stainless steel covers	\$	incl
6. Chassis Steps: ArcRite with Sure Grip	\$	1,000.00
7. Grille Guard: Ranch Hand Grille Guard	\$	incl
8. Siren Amplifier: Howler	\$	1,250.00
9. Window Tint on Chassis Doors	\$	250.00
10. Passenger's side Grille Light: Whelen M4 Red Light	\$	incl
11. Driver's side Grille Light: Whelen M4 Blue Light	\$	incl
12. Passenger's side 45 Intersect Light: Whelen M4 Clear Light	\$	incl
13. Passenger's side 90 Intersect Light: Whelen M4 Red Light	\$	250.00
14. Driver's side 45 Intersect Light: Whelen M4 Clear Light	\$	incl
15. Driver's side 90 Intersect Light: Whelen M4 Red Light	\$	250.00
16. UNOC #523 - Furnish and install foot switch on D/S for Howler	\$	200.00

Chassis Exterior Subtotal \$ 15,200.00

Module Exterior:

17. Onan 450 Hour Basic Preventative Maintenance	\$	incl
18. New Corner Caps	\$	incl
19. 10 hour(s) of Body Work	\$	1,000.00



Defining the future of Mobile Healthcare.™

20. Module Paint Layout: Single Stage White - Frazer White (BT650TS)	\$	14,500.00
21. Remove Conspicuity on Rear Wall	\$	600.00
22. Rear Wall 3M Conspicuity Layout - Chevron : Fluorescent Yellow/Green Base Color and Red - Translucent Overlay	\$	1,500.00
23. Entry Door Conspicuity Layout - Strips : Fluorescent Yellow/Green Base Color	\$	150.00
24. Compartment Conspicuity Layout - Strips : Fluorescent Yellow/Green Base Color	\$	150.00
25. Frazer Provided Graphics	\$	3,000.00
26. Existing GTT Opticom	\$	incl
27. Opticom Switching: On with Primary and Cut-off with door	\$	250.00
28. Install Ignition Kill Switch	\$	250.00
29. UNOC #343 - Furnish and install M6 load lights on the rear wall to replace existing - with converter flanged	\$	650.00
30. UNOC #350 - Furnish and install entire shore power line from electrical compartment to the outlet; leave 3' service loop	\$	400.00
31. Scene Light Option: Spectra SPA900	\$	1,500.00
32. New Lambda Power Supply	\$	1,500.00
33. Compartment Light in the Electrical Compartment	\$	250.00
34. Module Window Option: Sliding Window	\$	incl
35. Lower BTTs: 2 Grote Lights on each side	\$	incl
36. New Rear Bumper	\$	700.00
37. New Door Grabbers	\$	incl
38. New Cast License Plate Light	\$	incl
39. UNOC #524 - Discard shelf in the rear backboard compartment	\$	1,200.00
40. Replace Gas Hold-Open at Side Entry	\$	incl
41. Gas Hold Open on All Compartments	\$	750.00
Module Exterior Subtotal	\$	28,350.00

Chassis Interior:

42. Siren Speakers: Whelen SA 315 Speakers	\$	incl
43. Tap-2 on Primary Siren	\$	incl
44. Siren Option: Whelen C9 Siren in Console	\$	150.00
45. Mic 1 on on passenger's side slot 1	\$	incl
46. Console Layout: 4-Slot Console	\$	incl
47. Slot 1: Extended MDT plate - no swivel with fuel gauge	\$	50.00

48. Slot 2: Single Slot Switch Panel	\$	incl
49. Slot 3: Siren 1	\$	incl
50. Slot 4: Radio Plate Item ID 19868	\$	incl
51. Console Switch Layout : Primary - Secondary - Howler - Blank - Side Scene (Driver's Side) - Side Scene (Passenger's Side) - Rear Load - Interior Lights - Start/Stop Genset -	\$	incl
52. New Armrest	\$	200.00
53. Floor in Front of Console: Gamber Johnson Heavy Dual Cup Holder	\$	150.00
54. Rear of Console: Single Mapholder	\$	200.00
55. Chassis Rear Wall: 3 High Glove Box Holder	\$	200.00
56. Camera System: Replacement Rear View Mirror with Back-Up Camera	\$	1,600.00
57. White Back-up Camera	\$	incl
58. Aftermarket Vinyl Seats	\$	800.00
59. UNOC #237 - Remove and reinstall VHF Motorola XTL 2500 remote radio head in console slot #4 - Remove and reinstall speaker on the front of the console - Remove and reinstall mic on D/S of slot 2 - Reconnect to radio base in electrical compartment"	\$	200.00
60. UNOC #525 - Remove and reinstall cradlepoint router on the rear wall of the chassis behind the driver's seat Mounted on the B post under seat belt (wired battery hot) -Remove and reinstall (2) antenna's on chassis roof and run to cradlepoint - ensure the antenna IS NOT cross threaded on the cradle point - this will RUIN the modem	\$	400.00
61. UNOC #527 - Remove and reinstall swivel and docking station on MDT plate towards the right with Lind power supply in the console wired battery hot	\$	450.00
62. UNOC #526 - Remove and reinstall Nederman exhaust transmitter on the D/S of the console - wired ignition hot - Remove and SHIP LOOSE Nederman magnet on Genset door	\$	200.00
63. UNOC #528 - Furnish and install cup holder on the rear of the large map holder	\$	100.00
Chassis Interior Subtotal		\$ 4,700.00

Module Interior:

64. New Ceiling Lasco	\$	2,000.00
65. New Wall Lasco	\$	3,500.00
66. New Lexan for Front Wall and Action Wall Cabinets	\$	850.00
67. New Blue Interior Trim	\$	350.00
68. New Protek Cushions at the CPR Seat and Squad Bench	\$	1,350.00

69. UNOC 536 - Remove and reinstall medvault in the front corner area below the shelf flush with side of the front wall cabinet towards the back	\$	100.00
70. UNOC #537 - Remove and reinstall Knox Keysecure under front wall cabinet toward driver's side (wired battery hot)	\$	100.00
71. UNOC #538 - Remove and reinstall Vulcan flashlight charger on the front I/O shelf towards the front wall - wired battery hot	\$	100.00
72. UNOC #367 - Furnish and install lexan doors w/ Perko latches on existing Front I/O cabinet	\$	750.00
73. Action Wall Switch Layout : Interior Lights ; Front Interior Light ; Blank ;	\$	incl
74. Acrylic Holder at the Action Wall Cabinet	\$	250.00
75. New 6pt Harness at the CPR Seat	\$	500.00
76. Genset Start/Stop Swith at Rear Doors	\$	100.00
77. Rear Door Switch Layout : Acknowledge ; Start/Stop Genset ; Dump/Bypass (Suspension) ; Existing Rear Load ;	\$	incl
78. UNOC #183 - Non-standard switching for Interior LED's	\$	200.00
<ul style="list-style-type: none"> - ON/OFF interior light switch at the console that controls all of the interior LEDs - ON/OFF interior light switch at the action wall that controls all of the interior LEDs - HIGH/LOW interior light switch at the action wall that controls all of the interior LEDs rear end of the action wall just below the action wall cabinet - Remove and reinstall speaker on the behind the radio head - Remove and reinstall mic next to the radio at the action wall - Reconnect to radio base in electrical compartment 		
79. New Squad Bench Stainless	\$	700.00
80. Two Seating Positions at the Squad Bench - 1 and 3	\$	incl
81. 22 Pocket Acrylic Holder at Squad Bench	\$	600.00
82. Harness Type for Seat Position 1: New 6pt Harness	\$	500.00
83. Harness Type for Seat Position 3: New 6pt Harness	\$	500.00
84. New Trashcan at the Head of the Squad Bench	\$	incl
85. IV Hanger on Ceiling Raceway	\$	incl
86. Replace Overhead Grab Rail(s)	\$	incl
87. Replace Existing Squad Bench IV Hanger with New	\$	incl
88. Floor Options: Customer Provided Stryker Power-LOAD	\$	1,500.00
89. Stryker cot tower only (no antler and bar)	\$	incl
90. New Loncoin II Sapphire Floor	\$	3,250.00
91. Captain's Chair Type: Captain's Chair with Child Safety Seat and 4pt. Harness	\$	2,000.00



Defining the future of Mobile Healthcare.™

Module Interior Subtotal \$ 19,200.00

All Frazer Remounts come standard with the following features:

Replacement of applicable chassis components such as:

- Push Bar, Grill Lights, Siren, Speakers, & aluminum powder-coated console
- Backup alarm, generator fuel tank, and mud flaps

450 hour Preventative Maintenance on an Onan generator (if applicable)

Shear-plate method of attachment securing the module to the chassis

New LED Flex Strips to replace all existing compartment lights

Full electrical check

New weather-stripping, ribbed rubber & compartment bumpers

Complete detail of module